## Fugitive Dust Plan Inspections Corrective Actions Log 1Q 2019

Date	Form ID	Item Noted	Corrective Action Taken if Necessary	
			Curtain material ordered but not received on-site.	
			Replacement curtains will be installed once material	
All 1Q 2019	C-04	Missing some curtains at entrances	received.	
		Dust seal belt worn on the top cover (does		
1/6/2019 - 2/20/2019	C-04	not impact the sealing ability of belt seal)	No corrective action needed.	
1/7-9/2019	C-04	Some material piles underneath 10 belt	Piles cleaned on 1/9/2019	
1/13/2019	C-04	7-3 Conveyor scraper needs to be lowered	Issue repaired prior to next inspection	
1/16/2019	C-04	A belt screen on 9 belt needed repair	Issue repaired prior to next inspection	
2/3-5/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up by 2/5/2019	
2/10/2019	C-04	A belt screen on 9 belt needed repair	Work order generated to repair belt screen	
2/23/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up on 2/23/2019	
2/27/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up on 2/27/2019	
3/6/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up on 3/6/2019	
3/21-23/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up on 3/23/2019	
3/28-31/2019	C-04	Some material piles underneath 10 belt	Piles cleaned up on 3/31/2019	
1/12/2019	C-05	Cattle guards at entrance getting full	Cattle guards cleaned out on 1/12/2019	
		Concentrate storage area's 4" butterfly	Maintenance department corrected issue by loosening the	
3/20/2019	C-05	valve was not opening properly	valve flange and cutting the valve flange lip.	
			As soon as damage was discovered a purchase order was	
			generated to have 5D Mining & Construction (wind fence	
2/5/2040	0.40	Smelter slag screening area wind fence	installation contractor) come on-site and repair the	
2/5/2019	C-10	panels damaged	damages. All panels repaired on 2/12/2019.	
			Maintenance department found that the main water line to	
			the sprinklers was damaged. Once all the materials needed	
0/00/00/00 0/0/05:5		Reprocessed Slag Storage Area's sprinklers	to repair water line were procured. All of the damaged	
2/20/2019 - 3/3/2019	C-10	not operating at full GPM.	section of the water line was replaced by 3/3/2019.	
1/4 10/2010	C 12	Componential in a contract of the contract of	Once replacement curtain panels were received on-site they	
1/4-18/2019	C-12	Some missing curtain panels at entrance Water sprays did not turn on and noted that	were installed.	
1/10/2019	C-12	some were leaking	Water sprays were repaired on the same day.	
1/10/2019	C-12	Joine Wele leaking	I vvater sprays were repaired on the same day.	

2/16/2019	C-12	Water sprays were not functioning properly	Noted on 2/17/2019 that all sprays were functioning again
1/21/2019	S-02	Water sprays were not functioning properly	Repairs made on same day
All 1Q 2019	S-03	Broken latch on doors to bins #1 &3	Two work orders were generated. Work order #5000043940 was for repairing the bin door hinges and latches and work order #5000043942 was to replace gaskets. Final repairs are pending the receipt of replacement parts.
2/20-21/2019	S-06	Material piles underneath belts	Piles cleaned on 2/20/2019 and 2/21/2019
		Water line has a leak and needs to be	
2/18/2019	S-17	repaired	Leak in water line repaired on 2/18/2019